



Instrument Expert Original factory packaging www.dorgean.com

OPERATIONS MANUAL

ba76156e01 03/2014



TruLab pH 1310(P)

pH METER





For the most recent version of the manual, please visit <u>www.ysi.com</u>.

Contact YSI 1725 Brannum Lane Yellow Springs, OH 45387 USA Tel: +1 937-767-7241 800-765-4974 Email: <u>environmental@ysi.com</u> Internet: <u>www.ysi.com</u>

Copyright © 2014 Xylem Inc.

TruLab pH 1310 - Contents

1 Overview			·····	6	
	1.1	TruLa	ab pH 1310 meter	6	
	1.2	TruLa	ab pH 1310P meter with integrated printer	7	
	1.3	Sens	ors	7	
_				_	
2	Safe	ety	• • • • • • • • • • • • • • • • • • • •	8	
	2.1	Safet	ty information	8	
	2.	1.1	Safety information in the operating manual	8	
	2.	1.2	Safety signs on the meter	8	
	2.	1.3	Further documents providing safety information	8	
	2.2	Sate		9	
	2.	2.1	Authorized use	9	
	Z.	2.Z		9	
	Ζ.,	2.3		9	
3	Com	nmiss	ioning	10	
	3.1	Scop	e of delivery	10	
	3.2	Powe	er supply	10	
	33	Initia	l commissioning	10	
	3.	3.1	Inserting the batteries	11	
	3.	3.2	Connecting the power pack	12	
	3.	3.3	Mounting the stand	12	
4	One	ration		13	
-		Conc		12	
	4.1 4	1 1	Keynad	13 13	
	ч. 4	1.1	Disnlav	10	
	4	1.2	Status information (meter)		
	4.	1.4	Socket field	15	
	4.2	Swite	ching on the meter	15	
	4.3	Swite	ching off	16	
	4.4 Navigation				
	4.	4.1	Measured value display	16	
	4.	4.2	Operating modes	16	
	4.	4.3	Menus and dialogs	17	
	4.	4.4	Elements in menus and dialogs	17	
	4.	4.5	Example 1 on navigation: Setting the language	18	
	4.	4.6	Example 2 on navigation: Setting the date and time	20	

5	pH value	9		22
	5.1 Mea	asuring		22
	5.1.1	Measuring the pH value		22
	5.1.2	Measuring the temperature		24
	5.2 Cal	ibration		25
	5.2.1	Why calibrate?		25
	5.2.2	When do you have to calibrate?		25
	5.2.3	Automatic calibration (AutoCal)		25
	5.2.4	Manual calibration (ConCal)		28
	5.2.5	Calibration points		31
	5.2.6	Calibration data	• • • •	32
	5.2.7	Continuous measurement control (CMC function)	• •	34
6	ORP vol	tage		35
	61 Me	asuring		35
	6.1.1	Measuring the ORP		35
	6.1.2	Measuring the temperature		37
	6.2 OR	P calibration		37
	0.2 0.1			0.
7	Settings			38
	7.1 Mea	asurement settings		38
	7.1.1	Changing the settings for pH measurements		38
	7.1.2	Buffer sets for calibration		39
	7.1.3	Calibration interval		42
	7.2 Set	tings for ORP measurements		42
	7.3 Ser	nsor-independent settings		43
	7.3.1	System		43
	7.3.2	Data storage	• • • •	44
	7.4 Res	set		44
	7.4.1	Resetting the measurement settings		45
	7.4.2	Resetting the system settings		45
8	Data sto	prage		47
-	8.1 Mar	nual storage		47
	8.2 Aut	omatic storage at intervals		48
	83 Me	asurement data storage		50
	8.3.1	Editing the measured value storage		50
	8.3.2	Erasing the measurement data storage		52
	8.3.3	Measurement dataset		52
	8.3.4	Storage locations		52
0	Tranami	itting data (LICP interface)		E 2
9		iumy uala (USB interface)		53
	9.1 Opt	ions for data transmission	• • • •	53
	9.2 Cor			54
	9.3 Mul	tiLab Importer		54
10	Printer (only TruLab pH 1310P)		55
	10.1 Cor	nmissioning / switching the printer on or off		55

	 10.2 Operation / printing	56 56 56 56 57
11	Maintenance, cleaning, disposal	58
	11.1 Maintenance	58
	11.1.1 General maintenance activities	58
	11.1.2 Replacing the batteries	58
	11.2 Cleaning	59
	11.4 Disposal	59
12	What to do if	60
	12.1 pH/ORP	60
		02
13	Technical data	63
	13.1 Measuring ranges, resolution, accuracy	63
	13.2 General data	64
14	Firmware update	66
4 -	Classer	~7
15	Glossary	67
16	Index	69
17	Contact Information	71
	17.1 Ordering & Technical Support	71
	17.2 Service Information	71

1 Overview

1.1 TruLab pH 1310 meter

The compact TruLab pH 1310 precision pH meter enables you to perform pH measurements rapidly and reliably.

The TruLab pH 1310 provides the maximum degree of operating comfort, reliability and measuring certainty for all applications.

The USB interface can be used for data transmission to a PC and for software updates of the meter.



1.2 TruLab pH 1310P meter with integrated printer

The integrated printer of the TruLab pH 1310P enables to document measurements according to GLP requirements.



The information concerning the printer of the TruLab pH 1310P is given in a separate chapter (see section 10 PRINTER (ONLY TRULAB PH 1310P), page 55).



1.3 Sensors

A measuring system ready to measure consists of the TruLab pH 1310 meter and a suitable sensor.

Suitable sensors are pH electrodes and ORP electrodes.

2 Safety

2.1 Safety information

2.1.1 Safety information in the operating manual

This operating manual provides important information on the safe operation of the meter. Read this operating manual thoroughly and make yourself familiar with the meter before putting it into operation or working with it. The operating manual must be kept in the vicinity of the meter so you can always find the information you need.

Important safety instructions are highlighted in this operating manual. They are indicated by the warning symbol (triangle) in the left column. The signal word (e.g. "CAUTION") indicates the level of danger:

WARNING

indicates a possibly dangerous situation that can lead to serious (irreversible) injury or death if the safety instruction is not followed.



CAUTION

indicates a possibly dangerous situation that can lead to slight (reversible) injury if the safety instruction is not followed.

NOTE

indicates a possibly dangerous situation where goods might be damaged if the actions mentioned are not taken.

2.1.2 Safety signs on the meter

Note all labels, information signs and safety symbols on the meter and in the battery compartment. A warning symbol (triangle) without text refers to safety information in this operating manual.

2.1.3 Further documents providing safety information

The following documents provide additional information, which you should observe for your safety when working with the measuring system:

- · Operating manuals of sensors and other accessories
- Safety datasheets of calibration or maintenance accessories (such as buffer solutions, electrolyte solutions, etc.)

2.2 Safe operation

2.2.1 Authorized use

This meter is authorized exclusively for pH and ORP measurements in the laboratory.

Only the operation and running of the meter according to the instructions and technical specifications given in this operating manual is authorized (see section 13 TECHNICAL DATA, page 63).

Any other use is considered unauthorized.

2.2.2 Requirements for safe operation

Note the following points for safe operation:

- The meter may only be operated according to the authorized use specified above.
- The meter may only be supplied with power by the energy sources mentioned in this operating manual.
- The meter may only be operated under the environmental conditions mentioned in this operating manual.
- The meter may only be opened if this is explicitly described in this operating manual (example: Inserting the batteries).

2.2.3 Unauthorized use

The meter must not be put into operation if:

- it is visibly damaged (e.g. after being transported)
- it was stored under adverse conditions for a lengthy period of time (storing conditions, see section 13 TECHNICAL DATA, page 63).

3 Commissioning

3.1 Scope of delivery

- pH meter TruLab pH 1310
- 4 batteries 1.5 V Mignon type AA
- Power pack
- USB cable
- Stand
- Stand holder
- Comprehensive operating manual
- Short instructions
- CD-ROM with
 - USB drivers
 - comprehensive operating manual
 - software MultiLab Importer

3.2 Power supply

The TruLab pH 1310 is supplied with power in the following ways:

- Mains operation with the supplied power pack
- Battery operation (4 x alkaline manganese batteries, type AA)
- USB operation via a connected USB-B cable

3.3 Initial commissioning

Perform the following activities:

- Insert the supplied batteries
- For mains operation: Connect the power pack
- If necessary, mount a stand
- Switch on the meter (see section 4.2 SWITCHING ON THE METER, page 15)
- Set the date and time (see section 4.4.6 EXAMPLE 2 ON NAVIGATION: SETTING THE DATE AND TIME, page 20)

3.3.1 Inserting the batteries



You can operate the meter either with normal batteries or with rechargeable batteries (Ni-MH). In order to charge the batteries, an external charging device is required.



1. Open the battery compartment (1) on the underside of the meter.



- 2. Place four batteries (type Mignon AA) in the battery compartment.
- 3. Close the battery compartment (1).
- Set the date and time (see section 4.4.6 EXAMPLE 2 ON NAVIGATION: SETTING THE DATE AND TIME, page 20).

3.3.2 Connecting the power pack



CAUTION The line voltage at the operating site must lie within the input voltage range of the original power pack (see section 13 TECH-NICAL DATA, page 63).



CAUTION

Use original power packs only (see section 13 TECHNICAL DATA, page 63).

- 1. Connect the plug of the power pack to the socket for the power pack on the TruLab pH 1310.
- 2. Connect the original power pack to an easily accessible power outlet.

3.3.3 Mounting the stand

The stand base can be mounted at the right side of the meter.



4 Operation

4.1 General operating principles

4.1.1 Keypad

In this operating manual, keys are indicated by brackets <..>. The key symbol (e.g. **<ENTER>**) generally indicates a short keystroke (under 2 sec) in this operating manual. A long keystroke (approx. 2 sec) is indicated by the underscore behind the key symbol (e.g. **<ENTER__**>).

F1	<f1>: <f1>: <f2>:</f2></f1></f1>	Softkeys providing situation dependent functions, e.g.: <f1>/[Menu]: Opens the menu for measurement settings <f1>/[Menu]: Opens the menu for system settings</f1></f1>
	<f2>: <on off="">:</on></f2>	Switches the meter on or off
M	<m></m> :	Selects the measured parameter / Quits the settings
CAL	<cal>: <cal_>:</cal_></cal>	Calls up the calibration procedure Displays the calibration data
STO	<sto>: <sto>:</sto></sto>	Saves a measured value manually Opens the menu for the automatic save function
RCL	<rcl>: <rcl>:</rcl></rcl>	Displays the manually stored measured values Displays the automatically stored measured values
	< ▲ ><♥>: < ▲_ ><♥>:	Menu control, navigation Increments, decrements values Increments, decrements values continuously
ENTER	<enter>: <enter_>:</enter_></enter>	Opens the menu for measurement settings / confirms entries Opens the menu for system settings
AR	<ar></ar>	Freezes the measured value (HOLD function) Switches the AutoRead measurement on or off

4.1.2 Display



4.1.3 Status information (meter)

AR	Stability control (AutoRead) is active
HOLD	Measured value is frozen (<ar></ar> key)
	Batteries are almost empty

4.1.4 Socket field





Only connect sensors to the meter that cannot return any voltages or currents that are not allowed (> SELV and > current circuit with current limiting). Almost all customary sensors meet these requirements.

4.2 Switching on the meter

1. Press the **<On/Off>** key. The meter performs a self-test. The display shows the manufacturer's logo while the self-test is being performed.

The measured value display appears.



4.3 Switching off

1. Press the **<On/Off>** key.

Automatic switch-off function The instrument has an automatic switch-off function in order to save the batteries (see section 7.3.1 SYSTEM, page 43). The automatic switchoff switches off the measuring instrument if no key is pressed for an adjustable period.

The automatic switchoff is not active

- if the communication cable is connected
- if the Automatic data storage function is active, or with automatic data transmission
- if the power pack is connected

Display illumination The meter automatically switches off the display illumination if no key is pressed for 30 seconds. The illumination is switched on with the next keystroke again.

You can also generally switch the display illumination on or off (see section 7.3.1 SYSTEM, page 43).

4.4 Navigation

The principles of navigation in menus and dialogs are explained in the following sections.

4.4.1 Measured value display

In the measured value display, open the setting menus with the **<F1>** softkey. The current functions of the softkeys are shown on the display.

- Use <**F1**>/[Menu] (<u>short</u> pressure) to open the menu for calibration and measurement settings for the displayed measured parameter.
- Use <**F1__**>/[Menu] (<u>long</u> pressure (approx. 2 s) to open the *Storage & config* menu with the sensor-independent settings.

Use the keys of the keypad to carry out further functions such as storage or calibration (see section 4.1.1 KEYPAD, page 13). These functions are not available in other operating situations.

4.4.2 Operating modes

The meter has the following operating modes:

Operating mode	Description
Measuring	The measurement data of the connected sensor are shown in the measured value display
Calibration	The course of a calibration with calibration information, func- tions and settings is displayed
Storage in memory	The meter stores measuring data automatically or manually
Transmit- ting data	The meter transmits measurement data and calibration records to the USB interface automatically or manually.
Setting	The system menu or a sensor menu with submenus, set- tings and functions is displayed

4.4.3 Menus and dialogs

The menus for settings and dialogs in procedures contain further subelements.

- To select a subelement, use the <▲><▼> keys. The current selection is displayed with a frame.
- To make further settings, switch to the next higher menu level with **<F1>**[Back].
- Use **<M>** to return to the measured value display.

4.4.4 Elements in menus and dialogs

• <u>Submenus</u>

The name of the submenu is displayed at the upper edge of the frame. Submenus are opened by confirming with **<MENU/ENTER>**. Example:

System	
General	
Interface	
Clock	
Service information	
Reset	
Back 01.02.2014 08:00	

Settings

Settings are indicated by a colon. The current setting is displayed on the right-hand side. The setting mode is opened with **<MENU/ENTER>**. Subsequently, the setting can be changed with **<\Delta><\nabla> and <MENU/ENTER>**. Example:

General		
Language:		English
Beep:		Off
Illumination:		On
Contrast:		50 %
Switchoff time:		1 h
Back	01.02.2014 08:00	

• <u>Functions</u>

Functions are designated by the name of the function. They are immediately carried out by confirming with **<MENU/ENTER>**. Example: Display the *Calibration record* function.

pH Calibration record Calibration data storage Buffer: TEC One point calibration: Yes Calibration interval: 7 d Unit for slope: mV/pH Back 01.02.2014 08:00

<u>Messages</u>

Information is marked by the *i* symbol. It cannot be selected. Example:

рН	
Calibration record	
Calibration storage	
Buffer:	TEC
One point calibration:	Yes
Calibration interval:	7 d
Unit for slope:	mV/pH
i 2.00 4.01 7.00 10.01	
Back 01.02.2014 08:00	4

4.4.5 Example 1 on navigation: Setting the language

1. Press the **<On/Off>** key. The measured value display appears.

The instrument is in the measuring mode.



2. Using **<F1__**>/[Menu], open the *Storage & config* menu. The instrument is in the setting mode.

Storage & con	fig	
System		
Data storage		
Back	01.02.2014 08:00	

- 3. Select the *System* submenu with **<**▲**><**▼**>**. The current selection is displayed with a frame.
- 4. Open the System submenu with <MENU/ENTER>.

System
General
Interface
Clock
Service information
Reset
Back 01.02.2014 08:00

- 5. Select the *General* submenu with **<**▲**><**▼**>**. The current selection is displayed with a frame.
- 6. Open the *General* submenu with **<MENU/ENTER>**.

General		
Language:		English
Beep:		Off
Illumination:		On
Contrast:		50 %
Switchoff time:		1 h
Back	01.02.2014 08:00	

7. Open the setting mode for the *Language* with **<MENU**/ **ENTER>**.



- 8. Select the required language with $< \Delta > < \nabla >$.
- 9. Confirm the setting with **<MENU/ENTER>**. The meter switches to the measuring mode. The selected language is active.

4.4.6 Example 2 on navigation: Setting the date and time

The measuring instrument has a clock with a date function. The date and time are shown in the measured value display.

When storing measured values and calibrating, the current date and time are automatically stored as well.

The correct setting of the date and time and date format is important for the following functions and displays:

- Current date and time
- Calibration date
- Identification of stored measured values.

Therefore, check the time at regular intervals.



After a fall of the supply voltage (empty batteries), the date and time are reset.

The date format can be switched from the display of day, month, year (*dd.mm.yyyy*) to the display of month, day, year (*mm/dd/yyyy* or *mm.dd.yyyy*).

- In the measured value display: Using <F1__>/[Menu], open the Storage & config menu. The instrument is in the setting mode.
- 2. Select and confirm the *System* / *Clock* menu with <▲><▼> and <MENU/ENTER>.

The setting menu for the date and time opens up.

3. Select and confirm the *Time* menu with $< \Delta > < \nabla >$ and < MENU/ENTER>.

The hours are highlighted.

Clock		
Date format:		dd.mm.yyyy
Date:		01.02.2014
Time:		08:00:25
Back	01.02.2014 08:00	

- 4. Change and confirm the setting with $< \ge > < \forall >$ and < MENU/ENTER >. The minutes are highlighted.
- 5. Change and confirm the setting with $< \Delta > < \nabla >$ and < MENU/ENTER >. The seconds are highlighted.
- 6. Change and confirm the setting with $< \Delta > < \nabla >$ and < MENU/ENTER >. The time is set.
- 7. If necessary, set the *Date* and *Date format*. The setting is made similarly to that of the time.
- To make further settings, switch to the next higher menu level with [Back]<F1>.
 or
 Switch to the measured value display with <M>.
 The instrument is in the measuring mode.

5 pH value

- 5.1 Measuring
- 5.1.1 Measuring the pH value

When connecting an earthed PC, measurements cannot be performed in earthed media as the values would be incorrect. The USB interface is not galvanically isolated.



To ensure the high measurement accuracy of the measuring system, always measure with a calibrated electrode (see section 5.2 CALIBRATION, page 25).

- 1. Connect the pH electrode to the meter.
- 2. If necessary, select the measured parameter with <M>.
- When measuring without temperature sensor: Temper the test sample or measure the current temperature and enter it with <▲> <▼>.
- 4. Immerse the pH electrode in the test sample. The measured value is checked for stability (automatic stability control). The display of the measured parameter flashes.
- 5. Wait for a stable measured value. The display of the measured parameter no longer flashes.



Stability control (AutoRead) & HOLD function

The stability control function (*AutoRead*) continually checks the stability of the measurement signal. The stability has a considerable impact on the reproducibility of measured values.

The measured parameter flashes on the display

- as soon as the measured value is outside the stability range
- when the automatic Stability control is switched off.

You can activate or switch off the automatic *Stability control* function (see section 7.1.1 CHANGING THE SETTINGS FOR PH MEASUREMENTS, page 38).

 Freeze the measured value with <AR>. The [HOLD] status indicator is displayed. The HOLD function is active.



You can terminate the *Stability control* function and the HOLD function with **<AR>** or **<M>** at any time.

2. Using **<ENTER>**, activate the *Stability control* function manually. The [AR] status indicator appears while the measured value is assessed as not stable. A progress bar is displayed and the display of the measured parameter flashes.

The [HOLD][AR] status indicator appears as soon as a stable measured value is recognized. The progress bar disappears and the display of the measured parameter stops flashing.

The current measurement data is output to the interface. Measurement data meeting the stability control criterion is marked by AR.



You can prematurely terminate the *Stability control* function manually with **<ENTER>** at any time. If the *Stability control* function is prematurely terminated, the current measurement data are output to the interface without the AutoRead info.

3. Using **<ENTER>**, start a further measurement with stability control. or

Release the frozen measured value again with **<AR>** or **<M>**. The [AR] status display disappears. The display switches back to the previous indication.

Criteria for a stable measured value

The *Stability control* function checks whether the measured values are stable within the monitored time interval.

Measured parameter	Time interval	Stability in the time interval
pH value	15 seconds	Δ : Better than 0.01 pH
Temperature	15 seconds	Δ : Better than 0.5 °C

The minimum duration until a measured value is assessed as stable is the monitored time interval. The actual duration is mostly longer.

5.1.2 Measuring the temperature

For reproducible pH and ORP measurements, it is essential to measure the temperature of the test sample.

You have the following options to measure the temperature:

- Automatic measurement of the temperature with the temperature sensor (NTC30 or Pt1000) integrated in the sensor.
- Measurement with an external temperature sensor.
- Manual determination and input of the temperature.

The measuring instrument recognizes whether a suitable sensor is connected and automatically switches on the temperature measurement.

The display of the temperature indicates the active temperature measuring mode:

Temperature sensor	Resolution of the temp. display	Temp. measurement
yes	0.1 °C	Automatic with tempera- ture sensor
-	1 °C	Manual

If you wish to measure (or calibrate) without temperature sensor, proceed as follows:

- 1. Measure the current temperature of the test sample.
- Set the temperature value with <▲><▼>.
 or

In the <F1>/[Menu]/Man. temperature menu, set the temperature value with $< \Delta > < \nabla >$.

5.2 Calibration

5.2.1 Why calibrate?

pH electrodes age. This changes the zero point (asymmetry) and slope of the pH electrode. As a result, an inexact measured value is displayed. Calibration determines and stores the current values of the zero point and slope of the electrode.

Thus, you should calibrate at regular intervals.

5.2.2 When do you have to calibrate?

- After connecting a sensor
- Routinely within the framework of the company quality assurance
- When the calibration interval has expired

5.2.3 Automatic calibration (AutoCal)

Make sure that in the sensor menu, *Buffer* menu, the buffer set is correctly selected (see 7.1.1 CHANGING THE SETTINGS FOR PH MEASUREMENTS, PAGE 38).

Use any one to five buffer solutions of the selected buffer set in ascending or descending order.

Below, calibration with YSI buffers (YSI) is described. When other buffer sets are used, other nominal buffer values are displayed. Apart from that, the procedure is identical.



If single-point calibration was set in the menu, the calibration procedure is automatically finished with the measurement of buffer solution 1 and the calibration record is displayed.

- 1. Connect the pH electrode to the meter.
- Keep the buffer solutions ready. When measuring without temperature sensor: Temper the buffer solutions or measure the current temperature.
- In the measured value display, select the measured parameter pH or mV with <M>.
- Start the calibration with <CAL>. The calibration display for the first buffer appears (voltage display).



- 5. Thoroughly rinse the electrode with deionized water.
- 6. Immerse the electrode in the first buffer solution.
- When measuring without temperature sensor: Measure the temperature of the buffer and enter it with <▲><▼>.
- Start the measurement with <ENTER>. The measured value is checked for stability (stability control). The [AR] status indicator is displayed. A progress bar is displayed and the display of the measured parameter flashes.



Wait for the end of the measurement with stability control or accept the calibration value with <ENTER>.
 The calibration display for the part buffer appears (voltage display)

The calibration display for the next buffer appears (voltage display).

10. If necessary, finish the calibration procedure as a single-point calibration with **<M>**.

The calibration record is displayed.



For **single-point calibration**, the instrument uses the Nernst slope (-59.2 mV/pH at 25 °C) and determines the zero point of the electrode.

Continuing with twopoint calibration

- 11. Thoroughly rinse the electrode with deionized water.
- 12. Immerse the electrode in the second buffer solution.
- When measuring without temperature sensor: Measure the temperature of the buffer and enter it with <▲><▼>.

14. Start the measurement with **<ENTER>**.

The measured value is checked for stability (stability control). The [AR] status indicator is displayed. A progress bar is displayed and the display of the measured parameter flashes.



 Wait for the measurement with stability control to be completed or terminate the stability control and take over the calibration value with <ENTER>.

The calibration display for the next buffer appears (voltage display).

If necessary, finish the calibration procedure as a two-point calibration with <M>.
 The calibration record is displayed.

The calibration record is displayed.

Continuing with three- to five-point calibration

- 17. Thoroughly rinse the electrode with deionized water.
- 18. Immerse the electrode in the next buffer solution.
- When measuring without temperature sensor: Measure the temperature of the buffer and enter it with <▲><▼>.
- Start the measurement with <ENTER>. The measured value is checked for stability (stability control). The [AR] status indicator is displayed. A progress bar is displayed and the display of the measured parameter flashes.



21. Wait for the measurement with stability control to be completed or terminate the stability control and take over the calibration value with **<ENTER>**.

The calibration display for the next buffer appears (voltage display).

 If necessary, use <M> to finish calibration or Continue calibrating using the next buffer with <ENTER>.



Calibration is automatically completed after the last buffer of a buffer set has been measured. Then the calibration record is displayed.

The calibration line is determined by linear regression.

5.2.4 Manual calibration (ConCal)

Make sure that in the sensor menu, *Buffer* menu, the *ConCal* buffer set is selected (see section 7.1.1 CHANGING THE SETTINGS FOR PH MEASUREMENTS, page 38).

Use any one to five buffer solutions in ascending or descending order.



If single-point calibration was set in the menu, the calibration procedure is automatically finished with the measurement of buffer solution 1 and the calibration record is displayed.

- Connect the pH electrode to the meter. The pH measuring window is displayed.
- Keep the buffer solutions ready. When measuring without temperature sensor: Temper the buffer solutions or measure the current temperature.
- 3. In the measured value display, select the measured parameter pH or mV with **<M>**.
- 4. Start the calibration with **<CAL>**. The calibration display appears.



5. Thoroughly rinse the electrode with deionized water.

- 6. Immerse the electrode in the first buffer solution.
- When measuring without temperature sensor: Measure the temperature of the buffer and enter it with <▲><▼>.
- 8. Start the measurement with **<ENTER>**.
 - The measured value is checked for stability (stability control). The [AR] status indicator is displayed. A progress bar is displayed and the display of the measured parameter flashes.



9. Wait for the end of the measurement with stability control or accept the calibration value with **<ENTER>**.

The calibration display for the setting of the nominal buffer value appears.



- 10. Set the nominal buffer value for the measured temperature with $< \Delta > < \nabla >$.
- Accept the set calibration value with <ENTER>. The calibration display for the next buffer appears (voltage display).
- 12. If necessary, finish the calibration procedure as a single-point calibration with **<M>**.

The calibration record is displayed.



13.

For **single-point calibration**, the instrument uses the Nernst slope (-59.2 mV/pH at 25 °C) and determines the zero point of the electrode.

Continuing with twopoint calibration

Thoroughly rinse the electrode with deionized water.

- 14. Immerse the electrode in the second buffer solution.
- When measuring without temperature sensor: Measure the temperature of the buffer and enter it with <▲><▼>.
- 16. Start the measurement with **<ENTER>**. The measured value is checked for stability (stability control). The [AR] status indicator is displayed. A progress bar is displayed and the display of the measured parameter flashes.
- 17. Wait for the measurement with stability control to be completed or terminate the stability control and take over the calibration value with **<ENTER>**.

The calibration display for the setting of the nominal buffer value appears.



- 18. Set the nominal buffer value for the measured temperature with $< > < \forall >$.
- Accept the set calibration value with <ENTER>. The calibration display for the next buffer appears (voltage display).
- 20. Finish the calibration procedure as a two-point calibration with **<M>**. The calibration record is displayed.

Continuing with three- to five-point calibration

- 21. Thoroughly rinse the electrode with deionized water.
- 22. Immerse the electrode in the next buffer solution.
- When measuring without temperature sensor: Measure the temperature of the buffer and enter it with <▲><▼>.
- 24. Start the measurement with **<ENTER>**. The measured value is checked for stability (stability control). The [AR] status indicator is displayed. A progress bar is displayed and the display of the measured parameter flashes.
- 25. Wait for the measurement with stability control to be completed or terminate the stability control and take over the calibration value with **<ENTER>**.

The calibration display for the setting of the nominal buffer value appears.



- 26. Set the nominal buffer value for the measured temperature with $< > < \forall >$.
- 27. Accept the set calibration value with **<ENTER>**. The calibration display for the next buffer appears (voltage display).
- Use <M> to finish calibration or Continue calibrating using the next buffer with <ENTER>.



After the fifth buffer has been measured the calibration is automatically finished. Then the calibration record is displayed.

The calibration line is determined by linear regression.

5.2.5 Calibration points

Calibration can be performed using one to five buffer solutions in any order (single-point to five-point calibration). The meter determines the following values and calculates the calibration line as follows:

	Determined values	Displayed calibration data
1-point	Asy	 Zero point = Asy
		 Slope = Nernst slope (-59.2 mV/pH at 25 °C)
2-point Asy Slp.	 Zero point = Asy 	
	• Slope = <i>Slp.</i>	
3-point to	Asy	• Zero point = Asy
5-point Slp.	• Slope = <i>Slp.</i>	
		The calibration line is calculated by lin- ear regression.



You can display the slope in the units, mV/pH or % (see section 7.1.1 CHANGING THE SETTINGS FOR PH MEASUREMENTS, page 38).

5.2.6 Calibration data



The calibration record is automatically transmitted to the interface after calibrating.

Displaying the cali-
bration dataThe calibration record of the last calibration is to be found under the menu item,
<F1> / [Menu]Calibration / Calibration record. To open it, press the <CAL_>
key in the measured value display.

Subsequently, you can transmit the displayed calibration data to the interface, e. g. to a PC, with **<F2>**[USB output].

Displaying the calibration data storage

The calibration records of the last calibrations (up to 10) are available in the menu, <**F1**>/[Menu] / Calibration / Calibration data storage and in the menu, <**F1__**>/[Menu] / Storage & config/Data storage / Calibration data storage.

Menu item	Setting/func- tion	Description
Calibration / Calibration data stor- age /Display or Data storage / Calibration data stor- age /Display	-	 Displays the calibration record. Further options: Scroll through the calibration records with <▲><▼>. Output the displayed calibration record to the interface with <f2>/[USB output].</f2> Quit the display with <f1>/[Back] or <menu enter="">.</menu></f1> Switch directly to the mea-
		sured value display with <m></m> .
Calibration / Calibration data stor- age / Output to USB or	-	Outputs the calibration records to the interface.
Data storage / Calibration data stor- age /Output to USB		

Calibration evaluation

After calibrating, the meter automatically evaluates the calibration. The zero point and slope are evaluated separately. The worse evaluation of both is taken into account. The evaluation appears on the display and in the calibration record.

Display	Calibration record	Zero point [mV]	Slope [mV/pH]
Ć	+++	-15 +15	-60,558,0
đ H	++	-20 <-15 or >+15 +20	>-58,057,0
ő.	+	-25 <-20 or >+20 +25	-61,0 <-60,5 or >-57,056,0
۴ ا	-	-30 <-25 or ->+25 +30	-62,0 <-61,0 or >-56,050,0
Clean the electrode a electrode operating r	according to the manual		
Error	Error	-30 +30	-62,050,0
Error elimination (see TO DO IF, page 60)	e section 12 WHAT		

Calibration record (example)

inoLab TruLab pH 1310 Ser. no. 11292113 CALIBRATION pH 01.02.2014 15:55 Ser. no. 10501234 YSI Buffer 1 4.00 Buffer 2 7.00 Buffer 3 10.00 Voltage 1 184.0 mV 24.0 °C Voltage 2 3.0 mV 24.0 °C Voltage 3 -177.0 mV 24.0 °C Slope -60.2 mV/pH Asymmetry 4.0 mV Sensor +++

5.2.7 Continuous measurement control (CMC function)

The Continuous Measurement Control (CMC function) facilitates to evaluate the current measured value instantly and definitely.

After each successful calibration the scale of the pH measuring range is displayed in the measured value display. Here you can very clearly see whether or not the current measured value is in the calibrated part of the measuring range.

The following information is displayed:



The limits of the calibrated range are determined by the buffers used for calibration:

Lower limit:	Buffer with lowest pH value - 2 pH units
Upper limit:	Buffer with highest pH value + 2 pH units

6 ORP voltage

- 6.1 Measuring
- 6.1.1 Measuring the ORP

When connecting an earthed PC, measurements cannot be performed in earthed media as the values would be incorrect. The USB interface is not galvanically isolated.

- 1. Connect the ORP electrode to the meter.
- 2. If necessary, select the mV display with **<M>**.
- When measuring without temperature sensor: Measure the temperature of the test sample and enter it with <▲> <▼>.
- 4. Immerse the ORP electrode in the test sample. The measured value is checked for stability (automatic stability control). The display of the measured parameter flashes.
- 5. Wait for a stable measured value. The display of the measured parameter no longer flashes.



Stability control (AutoRead) The stability control function (*AutoRead*) continually checks the stability of the measurement signal. The stability has a considerable impact on the reproducibility of measured values.

You can activate or switch off the automatic *Stability control* function (see section 7.1.1 CHANGING THE SETTINGS FOR PH MEASUREMENTS, page 38).

The measured parameter flashes on the display

- as soon as the measured value is outside the stability range
- when you switch over between the measured parameters with <M>.
- when the automatic Stability control is switched off.

Criteria for a stable The *Stability control* function checks whether the measured values are stable within the monitored time interval.

Measured parame- ter	Time interval	Stability in the time interval
ORP voltage	15 seconds	Δ : Better than 0.3 mV
Temperature	15 seconds	Δ : Better than 0.5 °C

The minimum duration until a measured value is assessed as stable is the monitored time interval. The actual duration is mostly longer.

Manually starting the stability control

You can start the *Stability control* manually at any time, irrespective of the setting for automatic *Stability control* (see section 7.1.1 CHANGING THE SETTINGS FOR PH MEASUREMENTS, page 38) in the *Measurement* menu.

- Freeze the measured value with <AR>. The [HOLD] status indicator is displayed.
- 2. Using **<ENTER>**, activate the *Stability control* function manually. The [AR] status indicator appears while the measured value is assessed as not stable. A progress bar is displayed and the display of the measured parameter flashes.

The [HOLD][AR] status indicator appears as soon as a stable measured value is recognized. The progress bar disappears and the display of the measured parameter stops flashing.

The current measurement data is output to the interface. Measurement data meeting the stability control criterion is marked by AR.



You can prematurely terminate the *Stability control* function manually with **<ENTER>** at any time. If the *Stability control* function is prematurely terminated, the current measurement data are output to the interface without the AutoRead info.

3. Using **<ENTER>**, start a further measurement with *Stability control*. or

Release the frozen measured value again with **<AR>**. The display switches to the measured value display. The [AR][HOLD] status display disappears.

Freezing the measured value (HOLD function) With the HOLD function, you can freeze the current measured value. The displayed measured value stops changing until you switch the HOLD function off.



If the HOLD function is active, you can, e.g. start a manual measurement with stability control.

1. Freeze the measured value with **<AR>**. The [HOLD] status indicator is displayed.
Release the frozen measured value again with <AR>. The HOLD function is switched off. The [HOLD] status display disappears.

6.1.2 Measuring the temperature

For reproducible ORP measurements, it is essential to measure the temperature of the test sample.

You have the following options to measure the temperature:

- Automatic measurement of the temperature by the temperature sensor (NTC30 or Pt1000) integrated in electrode.
- Measurement by an external temperature sensor.
- Manual determination and input of the temperature.

The measuring instrument recognizes whether a suitable sensor is connected and automatically switches on the temperature measurement.

The display of the temperature indicates the active temperature measuring mode:

Temperature sensor	Resolution of the temp. display	Temp. measurement
yes	0.1 °C	Automatic with temper- ature sensor
-	1 °C	Manual

If you wish to measure (or calibrate) without temperature sensor, proceed as follows:

- 1. Measure the current temperature of the test sample.
- 2. Set the temperature value with $< > < \forall >$.

or

In the <F1>/[Menu]/Man. temperature menu, set the temperature value with < A>< V>.

6.2 **ORP** calibration



ORP electrodes are not calibrated. You can, however, check ORP electrodes by measuring the ORP of a test solution and comparing the value with the nominal value.

7 Settings

7.1 Measurement settings

7.1.1 Changing the settings for pH measurements

The settings are made in the menu for calibration and measurement settings of the pH/ORP measurement. To open the settings, display the required parameter in the measured value display and press the <F1>/[menu] or <MENU/ENTER> key. After completing the settings, switch to the measured value display with <M>.

Default settings are printed in **bold**.

Menu item	Possible set- ting	Description
Calibration /Cali- bration record	-	Displays the calibration record of the last calibration.
Calibration / Calibration data storage /Display	-	 Displays the calibration record. Further options: Scroll through the calibration records with <▲><▼>. Output the displayed calibration record to the interface with <f2>/[USB output].</f2> Output all calibration records to the interface with <f2>[USB output].</f2> Quit the display with <f1>/[Back] or <menu enter="">.</menu></f1>
		 Switch directly to the measured value display with <m>.</m>
Calibration / Cali- bration data stor- age / Output to USB	-	Outputs the calibration records to the interface.
Calibration / Serial number (probe)		 Entry of the serial number of the connected sensor. The serial number is output in the calibration record. Change the content of the high-lighted position with <▲><▼>. Go to the next position with <f2>/[▶].</f2> When the serial number has been completely entered, confirm with <enter>.</enter>

Menu item	Possible set- ting	Description
Calibration /Buffer	YSI ConCal NIST/DIN 	Buffer sets to be used for pH cali- bration (see section 5.2 CALIBRA- TION, page 25).
Calibration /One point calibration	Yes No	Quick calibration with 1 buffer
Calibration /Cali- bration interval	1 7 999 d	Calibration interval for the pH elec- trode (in days). The meter reminds you to calibrate regularly by the flashing sensor symbol in the measuring window.
Calibration /Unit for slope	тV/рН %	Unit of the slope. The % display refers to the Nernst slope of -59.2 mV/pH (100 x deter- mined slope/Nernst slope).
Man. temperature	-25 +25 +130 °C	Entry of the manually determined temperature. For measurements without temperature sensor only.
Temperature unit	°C °F	Temperature unit, degrees Celsius or degrees Fahr- enheit. All temperatures are displayed with the selected unit.
Resolution pH	0.001 0.01 0.1	Resolution of the pH display
Stability control	On Off	Switches on or off the automatic stability control during measure- ment (see section 5.1.1 MEASUR- ING THE PH VALUE, page 22)
Reset	-	Resets all sensor settings to the delivery condition (see section 7.4.1 RESETTING THE MEASURE-MENT SETTINGS, page 45).

7.1.2 Buffer sets for calibration

You can use the buffer sets quoted in the table for an automatic calibration. The pH values are valid for the specified temperature values. The temperature dependence of the pH values is taken into consideration during the calibration.

No.	Buffer set *	pH values	at
1	YSI*	4.000 7.000 10.000	25 °C
2	ConCal	Any	Any
3	NIST/DIN DIN buffers according to DIN 19266 and NIST Traceable Buffers	1.679 4.006 6.865 9.180 12.454	25 °C
4	<i>TEC</i> Technical buffers	2.000 4.010 7.000 10.011	25 °C
5	Merck 1*	4.000 7.000 9.000	20°C
6	Merck 2 *	1.000 6.000 8.000 13.000	20°C
7	Merck 3 *	4.660 6.880 9.220	20°C
8	Merck 4 *	2.000 4.000 7.000 10.000	20°C
9	Merck 5 *	4.010 7.000 10.000	25 °C
10	DIN 19267	1.090 4.650 6.790 9.230	25 °C
11	Mettler Toledo USA *	1.679 4.003 7.002 10.013	25 °C
12	Mettler Toledo EU *	1.995 4.005 7.002 9.208	25 °C

No.	Buffer set *	pH values	at
13	Fisher *	2.007 4.002 7.004 10.002	25 °C
14	Fluka BS *	4.006 6.984 8.957	25 °C
15	Radiometer *	1.678 4.005 7.000 9.180	25 °C
16	Baker *	4.006 6.991 10.008	25 °C
17	Metrohm *	3.996 7.003 8.999	25 °C
18	Beckman *	4.005 7.005 10.013	25 °C
19	Hamilton Duracal *	4.005 7.002 10.013	25 °C
20	Precisa *	3.996 7.003 8.999	25 °C
21	Reagecon TEC *	2.000 4.010 7.000 10.000	25 °C
22	Reagecon 20 *	2.000 4.000 7.000 10.000 13.000	20°C

No.	Buffer set *	pH values	at
23	Reagecon 25 *	2.000 4.000 7.000 10.000 13.000	25 °C
24	Chemsolute *	2,000 4,000 7,000 10,000	20 °C
25	USABlueBook *	4,000 7,000 10,000	25 °C

Brand names or trade names are trademarks of their respective owners protected by law.



The buffers are selected in the menu, pH / **<F1>**/[Menu] / *Calibration* / *Buffer* (see 7.1.1 CHANGING THE SETTINGS FOR PH MEASURE-MENTS, PAGE 38).

7.1.3 Calibration interval

The calibration evaluation is displayed as a sensor symbol.

The sensor symbol flashes after the adjusted calibration interval has expired. It is still possible to measure.



To ensure the high measuring accuracy of the measuring system, calibrate after the calibration interval has expired.

Setting the calibration interval The calibration interval is set to 7 days in the factory. You can change the interval (1 ... 999 days):

- 1. Open the menu for measurement settings with [Menu]<F1>.
- 2. In the *Calibration / Calibration interval* menu, set the calibration interval with <▲><▼>.
- 3. Confirm the setting with **<ENTER>**.
- 4. Quit the menu with **<M>**.

7.2 Settings for ORP measurements

The settings are made in the menu for calibration and measurement settings of the pH/ORP measurement. To open the settings, display the required parame-

ter in the measured value display and press the **<F1>**/[menu] or **<MENU**/ **ENTER>** key. After completing the settings, switch to the measured value display with **<M>**.

Default settings are printed in **bold**.

Menu item	Possible setting	Description
Man. temperature	-25 +25 +130 °C	Entry of the manually determined tem- perature. For measurements without temperature sensor only.
Temperature unit	°C °F	Temperature unit, degrees Celsius or degrees Fahrenheit. All temperatures are displayed with the selected unit.
Resolution mV	0.1 1	Resolution of the mV display
Stability control	On Off	Switches on or off the automatic stability control during measurement (see sec- tion Stability control (AutoRead) & HOLD function, page 22)
Reset	-	Resets all sensor settings to the delivery condition (see section 7.4.1 RESETTING THE MEASUREMENT SETTINGS, page 45).

7.3 Sensor-independent settings

7.3.1 System

To open the *Storage & config* menu, press the **<F1__>**[Menu] key in the measured value display. After completing the settings, switch to the measured value display with **<M>**.

Default settings are printed in **bold**.

Menu item	Possible set- ting	Description
System / General / Language	Deutsch English (further)	Selects the menu language
System / General / Beep	On Off	Switches on/off the beep on keystroke
System / General / Illumination	Auto On Off	Switches the display illumina- tion on/off
System / General / Contrast	0 50 100 %	Changing the display contrast

Menu item	Possible set- ting	Description
System / General / Switchoff time	10 min 1h 24 h	Adjusts the switch-off time
System / Interface / Baud rate	1200, 2400, 4800 , 9600, 19200	Baud rate of the data interface
System / Interface / Output format	ASCII CSV	Output format for data trans- mission (see section 9 TRANS- MITTING DATA (USB INTERFACE), page 53)
System / Interface / Decimal separator	Dot (xx.x) Comma (xx,x)	Decimal separator
System / Interface / Output header		Output of a header for Output format: CSV
System / Printer		Settings for the integrated prin- ter of the TruLab pH 1310 P. For details, see section 10 PRINTER (ONLY TRULAB PH 1310P), page 55
System /Clock	Date format Date Time	Time and date settings (see section 4.4.6 EXAMPLE 2 ON NAVIGATION: SETTING THE DATE AND TIME, page 20)
System /Service information		Hardware version and software version of the meter are dis- played.
System /Reset	-	Resets the system settings to the delivery condition (see sec- tion 7.4.2 RESETTING THE SYS- TEM SETTINGS, page 45).

7.3.2 Data storage

This menu contains all functions to display, edit and erase stored measured values and calibration records (see section 8 DATA STORAGE, page 47).

7.4 Reset

You can reset (initialize) all sensor settings and sensor-independent settings separately from each other.

7.4.1 Resetting the measurement settings



The calibration data are reset to the default settings together with the measuring parameters. Recalibrate after performing a reset.

The following settings for pH measurements are reset to the default settings with the *Reset* function:

Setting	Default settings
Buffer	YSI
Cal. interval	7 d
Unit for slope	mV/pH
Measured parameter	рН
Resolution pH	0.001
Resolution mV	0.1
Asymmetry	0 mV
Slope	-59.2 mV
Man. temperature	25 °C
One point calibration	No
Stability control	On
Temperature unit	°C

The sensor settings are reset under the *Reset* menu item in the menu for calibration and measurement settings. To open it, press the **<F1>**/[Menu] or **<MENU/ENTER>** key in the measured value display.

7.4.2 Resetting the system settings

The following system settings can be reset to the default condition:

Setting	Default settings
Language	English
Веер	On
Baud rate	4800 Baud
Output format	ASCII
Contrast	50 %
Illumination	Auto
Switchoff time	1 h

The system settings are reset in the menu, *Storage & config / System / Reset*. To open the *Storage & config* menu, press the **<F1__>**[Menu] key in the measured value display.

8 Data storage

You can transmit measured values (datasets) to the data storage:

- Manual storage (see section 8.1 MANUAL STORAGE, page 47)
- Automatic storage at intervals (see section 8.2 AUTOMATIC STORAGE AT INTERVALS, page 48)

Each storage process transmits the current dataset to the interface at the same time.

8.1 Manual storage

You can transmit a measurement dataset to the data storage as follows. The dataset is at the same time output to the interface:

 Press the **<STO>** key <u>shortly</u>. The menu for manual storage appears.

Manual da	ata storage 4 From 500
01.02.2014 1 pH 7.000 2	1:24:16 4.8 °C AR +++
ID number: Continue	1
Back) 01.02.2014 08:00

If necessary, change and confirm the ID number (1 ... 10000) with
 <▲><▼> and <MENU/ENTER>.
 The dataset is stored. The meter switches to the measured value dis-

If the storage is full The following window appears if all 500 storage locations are occupied:

Warning			
Data storage full. Erase?			
Yes			
Back 01.02.20 ⁷ 08:00	14		

play.

You have the following options:

- To erase the entire storage, confirm Yes.
- To cancel the storage process and switch to the measured value display, confirm *No*. Then you can e.g. transmit the stored data to a PC (see section 8.3.1 EDITING THE MEASURED VALUE STORAGE, page 50) and subsequently erase the storage (see section 8.3.2 ERASING THE MEASUREMENT DATA STORAGE, page 52).

8.2 Automatic storage at intervals

The storage interval (*Interval*) determines the time interval between automatic storage processes. Each storage process transmits the current dataset to the interface at the same time.

Configuring the automatic storage function

1.

Press the **<STO__>** key. The menu for automatic storage appears.



Settings You can configure the automatic storage function with the following settings:

Menu item	Possible set- ting	Description
ID number	1 10000	ID number for the dataset series.
Interval	1 s, 5 s, 10 s, 30 s, 1 min, 5 min, 10 min, 15 min, 30 min, 60 min	Storage interval. The lower limit of the storage interval can be restricted by the number of free storage locations. The upper limit is restricted by the storage duration.
Duration	1 min x min	Storage duration. Specifies after which time the automatic storage should be ter- minated. The lower limit of the storage duration is restricted by the stor- age interval. The upper limit is restricted by the number of free storage locations.

Starting the automatic storage function

To start the automatic storage function, select *Continue* with $<\Delta><\nabla>$ and confirm with <MENU/ENTER>. The meter switches to the measured value display.



The active automatic storage function can be recognized by the progress bar in the function display. The progress bar indicates the remaining storage duration.



If the automatic storage function is activated, only the following keys are active: Softkeys, **<M>**, **<STO__>** and **<On/Off>**. The other keys and the automatic switch-off function are deactivated.

Energy saving mode ([Eco mode])

If the automatic storing function is active, the meter provides an energy saving mode ([Eco mode]) to avoid unnecessary energy consumption. The energy

saving mode switches off functions of the meter that are not required for the automatic storage of measurement data (such as the display). By pressing any key the energy saving mode is switched off again.

Terminating the automatic storage function prematurely Proceed as follows to switch off the automatic storage function before the adjusted storage duration has expired:

1. Press the **<STO__>** key.

The following window appears.

Warning]		
Stop automatic storage?			
Yes			
No			
Back 01.02.2014 08:00			

 Using <▲><▼>, select Yes and confirm with <MENU/ENTER>. The meter switches to the measured value display. The automatic storage function is terminated.

8.3 Measurement data storage

8.3.1 Editing the measured value storage

The contents of the manual or automatic measurement data storage can be shown on the display and output to the interface.

Each of the measurement data storages has a function to erase the entire contents.

Editing the data storage The storage is edited in the menu, Storage & config / Data storage. To open the Storage & config menu, press the <F1_>[Menu] key in the measured value display.

Open the manual or automatic storage directly with the **<RCL>** or **<RCL_>** key.



The settings are explained here using the manual storage as an example. The same settings and functions are available for the automatic storage.

Settings	Menu item	Setting/ function	Description
	Data storage / Manual data storage / Display	-	Displays all measurement datasets page by page.
	Διοριαγ		 Further options: Scroll through the datasets with <▲><▼>.
			 Output the displayed dataset to the interface with <f2>/[USB output].</f2>
			 Quit the display with <f1>/ [Back].</f1>
	Data storage / Manual data storage / Erase	-	Erases the entire manual measure- ment data storage. All calibration data remains stored when this action is performed.
	Data storage / Manual data storage / Output to USB	-	Outputs all stored measurement data to the interface.

Display presentation of a dataset	Manual data storage 3 of 64 🜩		
	01.02.2014 11:24:16 ID number: 2		
	pH 7.000 24.8 °C AR +++		
	Back 01.02.2014 USB output		
Representation of a dataset (USB output)	01.02.2014 09:56:20 inoLab TruLab pH 1310 Ser. no. 08502113		
(COD Sulput)	ID number 2		
	pH 6.012 24.8 °C, AR, S: +++		
	01.02.2014 10:56:20 inoLab TruLab pH 1310 Ser. no. 08502113		
	ID number 2		
	pH 6.012 24.8 °C, AR, S: +++		
	etc		

Quitting the display To quit the display of stored measurement datasets, you have the following options:

- Switch directly to the measured value display with <M>.
- Quit the display and move to the next higher menu level with <F1>/[Back].

8.3.2 Erasing the measurement data storage

Erasing the measurement data storage (see section 8.3.1 EDITING THE MEASURED VALUE STORAGE, page 50).

8.3.3 Measurement dataset

A complete dataset consists of:

- ID number
- Date/time
- Measured value of the connected sensor
- Measured temperature value of the connected sensor or manually set temperature
- AutoRead info: The *AR* indicator appears with the measured value if the AutoRead criterion was met while storing (stable measured value). Otherwise, there is no *AR* indicator.
- Calibration evaluation: +++, ++, +, -, or no evaluation

8.3.4 Storage locations

The TruLab pH 1310 meter has two measurement data storages. The measured values recorded either manually or automatic are stored separately in individual measurement data storages.

Storage	Maximum number of datasets
Manual data storage	500
Automatic data storage	5000

9 Transmitting data (USB interface)

9.1 Options for data transmission

Via the USB interface you can transmit data to a PC. The following table shows which data are transmitted to the interface in which way:

Data	Control	Operation / description
Current	Manual	• With <f2< b="">>/[USB output].</f2<>
measured val- ues of all con- nected		 Simultaneously with every manual storage process (see section 8.1 MANUAL STORAGE, page 47).
	Automatic, at intervals	 With <f2_>/[USB output]. Then you can set the transmission interval.</f2_>
		 Simultaneously with every auto- matic storage process (see section 8.2 AUTOMATIC STORAGE AT INTER- VALS, page 48).
Stored mea- sured values	Manual	 Displayed dataset with <f2>[USB output] after calling up from the storage.</f2>
		 All datasets with the Output to USB function. (see section 8.3.1 EDITING THE MEASURED VALUE STORAGE, page 50).
Calibration records	Manual	 Calibration record with <f2>/[USB output] (see section 5.2.6 CALIBRATION DATA, page 32).</f2>
	Automatic	 At the end of a calibration proce- dure.



The following rule applies: With the exception of the menus, shortly pressing the $\langle F2 \rangle$ [USB output] key generally outputs the display contents to the interface (displayed measured values, measurement datasets, calibration records).

9.2 Connecting a PC

Connect the TruLab pH 1310 to the PC via the USB interface.

NOTE When connecting an earthed PC, measurements cannot be performed in earthed media as the values would be incorrect. The USB interface is not galvanically isolated. Installation of the USB driver on the PC PC with Pentium processor or higher with at least one free USB connection and CD-ROM drive Windows 2000, XP, Vista. 1. Insert the supplied installation CD in the CD drive of your PC.

2. Install the driver from the CD.

Follow the Windows installation instructions as necessary.

3. Connect the TruLab pH 1310 to the PC via the USB interface. The meter is listed as a virtual COM interface among the connections in the Windows instrument manager.

9.3 MultiLab Importer

With the aid of the MultiLab Importer software, you can record and evaluate measuring data with a PC.



More detailed information can be found in the MultiLab Importer operating manual.





10.1 Commissioning / switching the printer on or off

Switching on the printer

 Connect the power pack to the TruLab pH 1310 P. The LED lights up green. The printer is ready for operation. or If the printer was switched off (LED flashing): Switch on the printer with **<OFF>**. The LED lights up green. The printer is ready for operation.



1.

If there is a USB connection (such as to a PC) the data are output only to the PC.

Switching off the printer

Switch off the printer with **<OFF>**. The LED flashes. The printer is switched off.

10.2 Operation / printing

Data are only output to the printer if the following conditions are met

- Data are transmitted manually or automatically (see section 9.1 OPTIONS FOR DATA TRANSMISSION, page 53)
- the printer is switched on (LED illuminated)
- there is no USB connection.

10.3 Printer settings

To open the *Storage* & *config* menu, press the **<F1_>**[Menu] key in the measured value display. After completing the settings, switch to the measured value display with **<M>**.

Default settings are printed in **bold**.

Menu item	Possible set- ting	Description
System / Printer / Font size	12x20 8x16 7x16	Select the font size for the printer A print sample (character set of the printer) to view the available font sizes can be printed with <off_></off_> .
System / Printer / Print test page	-	The printer prints the meter informa- tion from the <i>System / Service infor- mation</i> menu. The current printer settings are used for the printout.

10.4 Maintenance

10.4.1 Changing the roll of paper (thermal paper)

- 1. Pull the lever (3) until the lid (4) of the paper compartment opens.
- 2. If necessary, remove any remains of the old roll of paper.
- 3. Insert the new roll of paper. The start of the paper should poke out of the paper compartment.
- 4. Close the lid (4) of the paper compartment so that it clicks into place.
- 5. If necessary, move the printer paper forward with **<ON/FEED>**.

section 9.1 OPTIONS FOR DATA TRANSMISSION, page 53)

Integrated printer	Cause	Remedy
does not print	 Printer switched off (LED flashing) 	 Switch on the printer (LED illuminated)
	 No power pack connected 	 Connect the power pack
	 USB cable connected 	 Disconnect the USB cable from the meter
	 Function "automatic storing at intervals" with long intervals is switched on 	 Switch off the function (see section 8.2 AUTOMATIC STORAGE AT INTER- VALS, page 48)
	 No paper available 	 Insert a roll of paper
Printer operating -	Cause	Remedy
paper not being printed	 Paper inserted the wrong way up 	 Turn the roll of paper around and insert it with the other side upwards
Integrated printer	Cause	Remedy
prints automatically	 The function "Automatic storage at intervals" or "Transmit data automatic at intervals" is 	 Switch off the function (see section 8.2 AUTOMATIC STORAGE AT INTER- VALS, page 48 or

10.5 What to do if... / printer

switched on

11 Maintenance, cleaning, disposal

11.1 Maintenance

11.1.1 General maintenance activities

The only maintenance activity required is replacing the batteries.



See the relevant operating manuals of the electrodes for instructions on maintenance.

11.1.2 Replacing the batteries



You can operate the meter either with normal batteries or with rechargeable batteries (Ni-MH). In order to charge the batteries, an external charging device is required.



- 1. Open the battery compartment (1) on the underside of the meter.
- 2. Remove the four batteries from the battery compartment.
- 3. Place four new batteries (type Mignon AA) in the battery compartment.



CAUTION

Make sure that the poles of the batteries are positioned correctly.

The \pm -signs on the batteries must correspond to the \pm signs in the battery compartment.

- 4. Close the battery compartment (1). The date (day) flashes on the display.
- 5. Set the date and time (see section 4.4.6 EXAMPLE 2 ON NAVIGATION: SETTING THE DATE AND TIME, page 20)



Dispose of used batteries according to the local regulations of your country.

End users within the European Union are obligated to return used batteries (even ecologically compatible ones) to a collection point set up for recycling purposes.

Batteries are marked with the crossed-out waste container symbol. Therefore, they may not be disposed with the domestic waste.

11.2 Cleaning

Occasionally wipe the outside of the measuring instrument with a damp, lintfree cloth. Disinfect the housing with isopropanol as required.



CAUTION

The housing is made of synthetic material (ABS). Thus, avoid contact with acetone or similar detergents that contain solvents. Remove any splashes immediately.

11.3 Packing

This meter is sent out in a protective transport packing. We recommend: Keep the packing material. The original packing protects the meter against damage during transport.

11.4 Disposal

At the end of its operational lifetime, the meter must be returned to the disposal or return system statutory in your country. If you have any questions, please contact your supplier.

12 What to do if...

12.1 pH/ORP



More information and instructions on cleaning and exchange of sensors are given in the documentation of your sensor.

Error message OFL, UFL

Cause	Remedy
pH electrode:	
– Air bubble in front of the junction	 Remove air bubble
 Air in the junction 	 Extract air or moisten junction
– Cable broken	 Replace electrode
- Gel electrolyte dried out	 Replace electrode
 Measured value outside the mea- suring range of the meter 	 Use suitable electrode

The measured value is outside the measuring range.

Error	message,
	Error

Cause	Remedy
pH electrode:	
 The values determined for zero point and slope of the electrode are outside the allowed limits. 	 Recalibrate
 Junction contaminated 	 Clean junction
 Electrode broken 	 Replace electrode
Buffer solutions:	
 Wrong buffer solutions 	 Change calibration procedure
 Buffer solutions too old 	 Use only once. Note the shelf life
 Buffer solutions depleted 	 Change solutions

No stable measured	Cause	Remedy					
value	pH electrode:						
	– Junction contaminated	– Clean junction					
	 Membrane contaminated 	 Clean membrane 					
	Test sample:						
	 pH value not stable 	 Measure with air excluded if necessary 					
	 Temperature not stable 	 Temper if necessary 					
	Electrode + test sample:						
	 Conductivity too low 	– Use suitable electrode					
	 Temperature too high 	- Use suitable electrode					
	 Organic liquids 	 Use suitable electrode 					
Obviously incorrect	Cause	Remedy					

	Cause	Remedy
measured values	pH electrode:	
	 pH electrode unsuitable 	 Use suitable electrode
	 Temperature difference between buffer and test sample too great 	 Adjust temperature of buffer or sample solutions
	 Measurement procedure not suit- able 	 Follow special procedure

Sensor symbol	Cause	Remedy
llasnes	 Calibration interval expired 	 Recalibrate the measuring system
Display	Cause	Remedy
	 Batteries almost empty 	 Replace the batteries (see section 11.1 MAINTENANCE, page 58)
Instrument does not	Cause	Remedy
react to keystroke	 Operating condition undefined or EMC load unallowed 	 Processor reset: Press the <enter></enter> and <on <="" b=""></on> Off> key simultaneously
You want to know	Cause	Remedy
version is in the meter	 E. g., a question by the service department 	 Switch on the meter. Open the menu, <f1_>/</f1_> [Menu] / Storage & config / SystemService information. The instrument data are displayed.

12.2 General information

13 Technical data

13.1 Measuring ranges, resolution, accuracy

Measuring ranges,	Parameter	Measuring ra	nge	Resolution					
resolution	рН	-2.0 +20.0		0.1					
		-2.00 +20.0	0	0.01					
		-2.000 +19.	999	0.001					
	U [mV]	-1200.0 +12	200.0	0.1					
		-2500 +2500							
	T [°C]	-5.0 +105.0		0.1					
	T [°F]	23.0 +221.0)	0.1					
Manual	Parameter	Range		Increment					
temperature input	T _{manual} [°C]	-25 +130		1					
	T _{manual} [°F]	-13 +266		1					
Accuracy (± 1 digit)	Parameter	Accuracy	erature of the test le						
	pH / range *								
	-2.0 +20.0	± 0.1	+15 °	C +35 °C					
	-2.00 +20.00	± 0.01	C +35 °C						
	-2.000 +19.999	± 0.005	+15 °	C +35 °C					
	U [mV] / range								
	-2500 +2500	± 1	+15 °	C +35 °C					
	-1200.0 +1200.0).0 ± 0.3 +15 °C +35 °C							
	T [°C] / temperature s	sensor							
	NTC 30	± 0.1							
	PT 1000	± 0.1							

* when measuring in a range of $\pm 2 \text{ pH}$ around a calibration point



The accuracy values specified here apply exclusively to the meter. The accuracy of the electrodes and buffer solutions has to be taken into account additionally.

Dimensions	TruLab pH 1310:	Approx. 230 x 190 x 80 mm
	TruLab pH 1310 P:	Approx. 280 x 230 x 80 mm
Weight	TruLab pH 1310:	Approx. 0.8 kg
	TruLab pH 1310 P:	Approx. 1.0 kg
Mechanical structure	Type of protection	IP 43
Electrical safety	Protective class	III
Test certificates	CE, cETLus	
Ambient	Storage	-25 °C +65 °C
conditions	Operation	+5 °C +55 °C With the power pack connected: +5 °C +40 °C
	Admissible relative humidity	Yearly mean: < 75 % 30 days/year: 95 % Other days: 85 %
Power supply	Batteries	4 x 1.5 V alkali-manganese batteries, type AA
	Rechargeable batter- ies	4 x 1.2 V NiMH rechargeable batteries, type AA (no charging function)
	Operational life	Up to 1000 h without / 150 h with illumination
	Power pack	Kuantech Co. Ltd. KSAC 0900110W1UV-1 Input: 100 240 V ~ / 50 60 Hz / 270 mA
		Output: 9 V = / 1.1 A Connection max. overvoltage category II Primary plugs contained in the scope of delivery: Euro, US, UK and Australian.
Sensor input	Input resistance	Output: 9 V = / 1.1 A Connection max. overvoltage category II Primary plugs contained in the scope of delivery: Euro, US, UK and Australian.
Sensor input	Input resistance Input current	Output: 9 V = / 1.1 A Connection max. overvoltage category II Primary plugs contained in the scope of delivery: Euro, US, UK and Australian. > 5 * 10 ¹² ohm < 1 * 10 ⁻¹² A
Sensor input	Input resistance Input current Type	Output: 9 V = / 1.1 A Connection max. overvoltage category II Primary plugs contained in the scope of delivery: Euro, US, UK and Australian.> 5 * 10 ¹² ohm< 1 * 10 ⁻¹² AUSB 1.1 USB B (device), data output
Sensor input	Input resistance Input current Type Baud rate	Output: 9 V = / 1.1 A Connection max. overvoltage category II Primary plugs contained in the scope of delivery: Euro, US, UK and Australian.> 5 * 10^{12} ohm< 1 * 10^{-12} AUSB 1.1 USB B (device), data outputAdjustable: 1200, 2400, 4800, 9600, 19200 Baud
Sensor input	Input resistance Input current Type Baud rate Data bits	Output: 9 V = / 1.1 A Connection max. overvoltage category II Primary plugs contained in the scope of delivery: Euro, US, UK and Australian. > 5 * 10 ¹² ohm < 1 * 10 ⁻¹² A USB 1.1 USB B (device), data output Adjustable: 1200, 2400, 4800, 9600, 19200 Baud 8
Sensor input	Input resistance Input current Type Baud rate Data bits Stop bits	Output: 9 V = / 1.1 A Connection max. overvoltage category II Primary plugs contained in the scope of delivery: Euro, US, UK and Australian.> 5 * 10^{12} ohm< 1 * 10^{-12} AUSB 1.1 USB B (device), data outputAdjustable: 1200, 2400, 4800, 9600, 19200 Baud8 2
Sensor input USB interface	Input resistance Input current Type Baud rate Data bits Stop bits Parity	Output: 9 V = / 1.1 A Connection max. overvoltage category II Primary plugs contained in the scope of delivery: Euro, US, UK and Australian.> 5 * 10^{12} ohm< 1 * 10^{-12} AUSB 1.1 USB B (device), data outputAdjustable: 1200, 2400, 4800, 9600, 19200 Baud8 2 None
Sensor input	Input resistance Input current Type Baud rate Data bits Stop bits Parity Handshake	Output: 9 V = / 1.1 A Connection max. overvoltage category II Primary plugs contained in the scope of delivery: Euro, US, UK and Australian.> 5 * 10^{12} ohm< 1 * 10^{-12} AUSB 1.1 USB B (device), data outputAdjustable: 1200, 2400, 4800, 9600, 19200 Baud8 2 None RTS/CTS

13.2 General data

Guidelines and norms used

EMC	EC directive 2004/108/EC
	EN 61326-1
	EN 61000-3-2
	EN 61000-3-3
	FCC Class A
Meter safety	EC directive 2006/95/EC
	EN 61010-1
	UL 61010-1
	CAN/CSA-C22.2#61010-1
IP protection class	EN 60529

FCC Class A Equipment Statement

<u>Note:</u> This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at his own expense.

Changes or modifications not expressly approved by the manufacturer could void the user's authority to operate the equipment.

14 Firmware update

Available firmware updates are provided on the Internet. With the firmware update program and a PC you can update the firmware of the TruLab pH 1310 to the newest version.

For the update you have to connect the meter to a PC.

For the update via the USB interface, the following is required:

- a free USB interface (virtual COM port) on the PC
- the driver for the USB interface (on the enclosed CD-ROM)
- the USB cable (included in the scope of delivery of the TruLab pH 1310).
- Install the downloaded firmware update on a PC. An update folder is created in the Windows start menu. If an update folder already exists for the meter (or meter type), the new data is displayed there.
- 2. In the windows start menu, open the update folder and start the firmware update program.
- 3. Using the USB interface cable, connect the TruLab pH 1310 to a USB interface (virtual COM port) of the PC.
- 4. Switch on the TruLab pH 1310.
- 5. In the firmware update program, start the update process with OK.
- Follow the instructions of the firmware update program. During the programming process, a corresponding message and a progress bar (in %) are displayed. The programming process takes approx. three minutes. A terminatory message is displayed after a successful programming process. The firmware update is completed.
- Disconnect the TruLab pH 1310 from the PC. The TruLab pH 1310 is ready for operation again.

After switching the meter off and on you can check whether the meter has taken over the new software version (see YOU WANT TO KNOW WHICH SOFTWARE VERSION IS IN THE METER, PAGE 62).

15 Glossary

pH/ORP

Asymmetry	see zero point
Electromotive force of an electrode	The electromotive force U of the combination electrode is the measur- able electromotive force of an electrode in a solution. It equals the sum of all the galvanic voltages of the combination electrode. Its dependency on the pH results in the electrode function, which is char- acterized by the parameters, slope and zero point.
Junction	The junction is a porous body in the housing wall of reference elec- trodes or electrolyte bridges. It arranges the electrical contact between two solutions and makes the electrolyte exchange more dif- ficult. The expression, junction, is also used for ground or junction- less transitions.
ORP voltage	The ORP is caused by oxidizing or reducing substances dissolved in water if these substances become effective on an electrode surface (e. g. a gold or platinum surface).
pH value	The pH value is a measure of the acidic or basic effect of an aqueous solution. It corresponds to the negative decadic logarithm of the molal hydrogen ions activity divided by the unit of the molality. The practical pH value is the value of a pH measurement.
Potentiometry	Name of a measuring technique. The signal (depending on the mea- sured parameter) of the electrode is the electrical potential. The elec- trical current remains constant.
Slope	The slope of a linear calibration function.
Zero point	The zero point of a pH combination electrode is the pH value at which the electromotive force of the pH combination electrode at a specified temperature is zero. Normally, this is at 25 °C.

General information

Adjusting	To manipulate a measuring system so that the relevant value (e.g. the displayed value) differs as little as possible from the correct value or a value that is regarded as correct, or that the difference remains within the tolerance.
AutoRange	Name of the automatic selection of the measuring range.
Calibration	Comparing the value from a measuring system (e.g. the displayed value) to the correct value or a value that is regarded as correct. Often, this expression is also used when the measuring system is adjusted at the same time (see adjusting).
Measured parameter	The measured parameter is the physical dimension determined by measuring, e. g. pH, conductivity or D.O. concentration.

Measured value	The measured value is the special value of a measured parameter to be determined. It is given as a combination of the numerical value and unit (e. g. 3 m; 0.5 s; 5.2 A; 373.15 K).
Molality	Molality is the quantity (in Mol) of a dissolved substance in 1000 g solvent.
Reset	Restoring the original condition of all settings of a measuring system.
Resolution	Smallest difference between two measured values that can be dis- played by a meter.
Stability control (AutoRead)	Function to control the measured value stability.
Standard solution	The standard solution is a solution where the measured value is known. It is used to calibrate a measuring system.
Temperature function	Name of a mathematical function expressing the temperature behav- ior of a test sample, a sensor or part of a sensor.
Test sample	Designation of the test sample ready to be measured. Normally, a test sample is made by processing the original sample. The test sample and original sample are identical if the test sample was not processed.

16 Index

Α

Automatic switch-off	16
ORP	35
рН	22

В

Battery compartment			•			•	 . 1	1,	58	3

С

Calibration	
рН	37
Calibration evaluation	
рН	32
Calibration interval	42
Calibration points	
рН	31
Connecting a PC	54

D

Dataset	52
Date and time	20
Default settings	
Measured parameter	45
System settings	45

Ε

Energy saving mode	 9

F

Firmware update			•	•		•	•	•	•	•		•	•		•		•			•	6	6
-----------------	--	--	---	---	--	---	---	---	---	---	--	---	---	--	---	--	---	--	--	---	---	---

I

Initial commissioning								10
Initialize								44
Interval for calibration								42

Κ

Keys	Keys			•		•				•		•			•			•		•	•													1	3
------	------	--	--	---	--	---	--	--	--	---	--	---	--	--	---	--	--	---	--	---	---	--	--	--	--	--	--	--	--	--	--	--	--	---	---

Μ

Measured value display	16
Measurement accuracy	42
Measurement data storage	
Edit	50
Erase	50
Measurement dataset	52

Measuring	
ORP voltage	35
рН	22
Menus (navigation)	17
Messages	18

Ρ

pH buffer sets	39
Print	53
Printer (only pH 7310P)	55

R

D 4															
Reset .															44

S

14
10
29
25
15
48
47
48
47

Т

Temperature measurement
pH 24, 37
Three-point calibration
pH 27, 30
Transmitting data 53
automatic
manual 53
Transmitting measured values 53
Two-point calibration
рН 26, 29

Ζ

Zero point of pH combination electrode ... 25

17 Contact Information

17.1 Ordering & Technical Support

<u>Telephone</u> :	(800) 897-4151 (937) 767-7241 Monday through Friday, 8:00 AM to 5:00 PM ET
<u>Fax</u> :	(937) 767-1058
<u>Email</u> :	environmental@ysi.com
<u>Mail</u> :	YSI Incorporated 1725 Brannum Lane Yellow Springs, OH 45387 USA
Internet:	www.ysi.com

When placing an order please have the following information available:

YSI account number (if available)	Name and Phone Number
Model number or brief description	Billing and shipping address
Quantity	Purchase Order or Credit Card

17.2 Service Information

YSI has authorized service centers throughout the United States and Internationally. For the nearest service center information, please visit <u>www.ysi.com</u> and click 'Support' or contact YSI Technical Support directly at 800-897-4151.

When returning a product for service, include the Product Return form with cleaning certification. The form must be completely filled out for an YSI Service Center to accept the instrument for service. The Product Return form may be downloaded at <u>www.ysi.com</u> and clicking on the 'Support' tab.




Xylem |'zīləm|

The tissue in plants that brings water upward from the roots;
a leading global water technology company.

We're 12,500 people unified in a common purpose: creating innovative solutions to meet our world's water needs. Developing new technologies that will improve the way water is used, conserved, and re-used in the future is central to our work. We move, treat, analyze, and return water to the environment, and we help people use water efficiently, in their homes, buildings, factories and farms. In more than 150 countries, we have strong, long-standing relationships with customers who know us for our powerful combination of leading product brands and applications expertise, backed by a legacy of innovation.

For more information on how Xylem can help you, go to www.xyleminc.com



YSI 1725 Brannum Lane Yellow Springs, OH 45387 Tel: +1 937-767-7241; 800-765-4974 Fax: +1 937-767-1058 Email: environmental@ysi.com Web: www.ysi.com

©Xylem Inc